


TRACTOR SPECS

All tractors must conform to the smoke tube dimensions. No obstructions may exist (ROPS, roll cage to pipe height, pipe brace, etc.). Should you not be able to meet these requirements, you will not be permitted to hook and entries will be forfeited.




Brace must be at least 36 inches from the end of the tube!



You **MUST** have a minimum of 12" clearance between top of roll cage/ROPS to the bottom of the smoke tube. 17" is preferred.

All bolts in top of the smoke tube brace brackets must be installed threaded end down and away from the outer liner of the sled tube.

TRUCK SPECS



**FRONT LIFT PLATES FOR ALL DIESEL OR ALCOHOL TRACTORS
(SS/PS, SUPER FARM, PRO FARM, MOD TURBO/LIM PRO, LT LIM TURBO,
ALL OPEN TRACTORS)**

It is mandatory to have these lift plates on your tractor for the track equipment personnel to maneuver you around the pits, hook you to the sled and remove you from the track.

The plate must be steel material with a 3" diameter hole in the center built heavy enough and fastened in a way to support the weight of your vehicle. The plate must be mounted at the front most point of your vehicle and unobstructed by weights or anything else.

